## मदन मोहन मालवीय प्रौद्योगिकी विश्वविद्यालय गोरखपुर।

### आवश्यक सूचना

अवगत कराना है कि आवासीय परिसर के आवासों के विशेष अनुरक्षण कार्य के अन्तर्गत आवासों में कार्यदायी संस्था के द्वारा निरीक्षण के उपरान्त प्रस्तावित कार्य की इन्वेन्ट्री तैयार कर प्रस्तुत की गयी, जिसके अनुसार प्रत्येक आवास में कार्य कराया जाना है। उक्त के अतिरिक्त कोई भी कार्य इस योजना के अन्तर्गत सम्मिलित नहीं किया जायेगा। यदि किसी आवास में उक्त प्रस्तावित सूची के अतिरिक्त कार्य की आवश्यकता है, तो अनुमन्य व्यय सीमा तक उस कार्य का पृथक से सक्षम स्तर से अनुमोदन प्राप्त करने के उपरान्त ही सम्मिलित किया जायेगा। इसके साथ ही विश्वविद्यालय प्रशासन द्वारा उक्त कार्य को कराये जाने हेतु प्रयोग होने वाली सामग्री की अनुमोदित ब्राड आदि की सूची इस आशय से संलग्न प्रेषित है कि प्रत्येक आवासित द्वारा सुनिश्चित किया जाए कि आवास में उक्तानुसार ही आवासों में निर्माण सामग्री का प्रयोग किया जा रहा है।

अतएव परिसर के आवासों में आवासित समस्त शिक्षकों, अधिकारियों एवं कर्मचारियों से अपेक्षा की जाती है कि उक्त इन्वेन्ट्री के अनुसार आवासों में कार्य कराये जाने में सहयोग प्रदान करने का कष्ट करें, साथ ही कार्य पूर्ण होने के उपरान्त उक्त इन्वेन्ट्री एवं सामग्री की सूची के आधार पर ही अपने आवास में हुए कार्यों का सत्यापन करना सुनिश्चित करें। साथ ही इस बात का विशेष ध्यान रखा जाए कि आवासों में पूर्व में ही विश्वविद्यालय स्तर से अथवा आपके स्वयं के स्तर से कराये गये मरम्मत के कार्यों का सत्यापन न किया जाए।

संलग्नकः

- 01 आवासवार प्रस्तावित मरम्मत कार्य की इन्वेन्ट्री।
- 02 कार्य हेत् प्रयुक्त होने वाली सामग्री की अनुमोदित सूची।

कुलसचिव

पृं0स0/मा0प्रौ0वि0/कुस0का0/ 332 /2023

दिनांकः 03 मई 2023

प्रतिलिपि निम्न को सुचनार्थ एवं आवश्यक कार्यवाही हेत् प्रेषित :-

- 01 परिसर के आवासों में आवासित समस्त शिक्षकगण/ अधिकारीगण/ कर्मचारीगण।
- 02 अधिष्ठाता, नियोजन, स्त्रोत जनन एवं पुरातन छात्र सम्बन्ध।
- 03 सदस्य-सचिव, भवन कार्य समिति / विभागाध्यक्ष, जनपदीय अभि0 विभाग।
- 04 वित्त नियन्त्रक।
- 05 सहायक अभियन्ता।
- 06 अधिशासी अभियन्ता, यू०पी०आर०एन०एस०एस०एल०, गोरखपुर।
- 07 वेबमास्टर, विश्वविद्यालय बेबसाईट को इस आशय से कि उक्त सूचना को संलग्नकों सहित आवासितों के सूचनार्थ अपलोड करने हेतु।
- 08 वै0 सहायक, कुलपति को मा0 कुलपति महोदय के सादर अवलोकनार्थ।

कुलसमिव ०५ १०१३

# Agency: UPRNSS-Nirman Prakhand-I, Gorakhpur

Name of Work: Special Replar MMUT, Gorakhpur

| Sr. No.                               | İtem                                  | Proposed   | Approved by  |
|---------------------------------------|---------------------------------------|--|--------------|
|                                       |                                       |  | MMUT         |
| 1                                     | Brick (7)                             | MR AK SS   | RKSS         |
| 2                                     | Coarse Sand (7,8,9,10,14,15)          | Unbranded  | AL ROY ED    |
| 3                                     | Cement (7,8,9,10,14,15,16,17)         | Ultrateck, Birla, KJS  | Ullya-Te     |
| 4                                     | Stone Grit (8,9,10,14)                | Unbranded  | As los RE    |
| 5                                     | Mild Steel (19,20)                    | Gallant  | Gallant      |
| 6                                     | Veterified Tiles (15)                 | Kajaria K-6000,6101,6002   | Kararêa      |
| 7                                     | Saal Wood (17,18)                     | Unbranded  | TAGES ES     |
| 8                                     | Secon class Teak Wood (22,24)         | Unbranded  | LAS SON ED   |
| 9                                     | Solid Door Shutter                    | Solid  | Santlen      |
| 10                                    | UPVC Vent                             |  | sample not   |
| 11                                    | Flush Door (25,28,29,30,31)           | Zender Shatabdal 3   | Omn          |
| 12                                    | Granite Stone (30)                    | Unbranded  | A> 01-10-76  |
| 13                                    | Ceramic Floor Tiles (37,38)           | Kajaria  | Kazarea      |
| -14                                   | Wall Putty                            | Burger, J.K., Birla  |              |
| 15                                    | Distemper                             | Burger, Dulex  | I BURGER     |
| -                                     | Exterior Paint                        | Burger, Dulex & Appro  | I Burger     |
| -17                                   | Water Proofing Membrane (49)          | Fosroc, Burger   | Sanfile That |
| herinan viorabilitari dalla latte for | Kota Stone (51)                       | The state of the s | Sarterno     |
| ntervances and consistent dis-        | Sanitory Work                         | HindWare ,Cera ~   | Hendwa       |
| until receivables standardens für     | CPVC Pipes (12)                       | Prakash, Prince  | Prokask      |
| minimum years of a                    | SS Kitchan Sink                       | Tata, Jindal   | ATAT         |
|                                       | CP Brass.Bib Cock (20,23,27,28,29,30) | no financial de la company br>La K   |              |
| marine and a                          | CP Shower                             | I.K  | LXK.         |
|                                       | W/C Pan (25)                          | HindWare,Cera V  | JURIA GOA    |
|                                       | GI Fitting (13,14,15,16)              | . ISI Mark   | DATA PER     |
| 7                                     | Rane Water Pipe (31,32,33)            | Prakash  | Prakasi      |

अवर अभियन्ता यू भी आर.पन ६स एम नामाष्ट्र पंखण्डः गोरखपुर उपम

भरायके आंभवस्या यू.वा.आर.एन.एस.एस.

मुरक्षीर (वसम)

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | V-04, D-01, W-07   |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)   | 4                                       | 4  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | 01   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | l                                       | 01   |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | 01   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 01   |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | 02   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | 01   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site |
|------------|---|---|---|
|            |   |   | requirement                                 |
| A          | Civil works   |   | · · · · · · · · · · · · · · · · · · ·       |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm                                  |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm                                      |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm                                   |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W1,D1                                       |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | V-04,                                       |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required                                |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required                                    |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required                                |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm                                  |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | Not Required                                |
| 12         | UPVC Vent (26)  | 4                                       | 4   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm                                  |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm                                   |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm                                   |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm                                    |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm                                   |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                    |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required                                |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm                                    |
| 19         | Drain Courtyard (6,7,16,17)   |   | and and                                     |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required                                |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required                                |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm                                  |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required                                    |
| 24         | Septic Tank   | Not Proposed                            | Not Required                                |
| 25         | Soak Pit  | Not Proposed                            | Not Required                                |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm                                  |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm                                      |
| В          | Sanitary/Sewage/Water Supply System   |   |   |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required                                |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required                                |
| 3          | Sink Stainless steel (22)   | 1                                       | 1   |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required                                |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required                                |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required                                |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1   |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required                                |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required                                |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required                                |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required                                |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m                                       |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required                                |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site |
|------------|---|---|---|
| ٠.         | (12 23 112)   | F                                       | requirement                                 |
| A          | Civil works   |   |   |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm                                  |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm                                      |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm                                   |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W1,D1                                       |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | V-04,D-01,W-04                              |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required                                |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required                                    |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required                                |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm                                  |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | Not Required                                |
| 12         | UPVC Vent (26)  | . 4                                     | 4   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm                                  |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm                                   |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm                                   |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm                                    |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm                                   |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                    |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required                                |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm                                    |
| 19         | Drain Courtyard (6,7,16,17)   |   | 1 - 1 AL 1 105                              |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required                                |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required                                |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm                                  |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required                                    |
| 24         | Septic Tank   | Not Proposed                            | Not Required                                |
| 25         | Soak Pit  | Not Proposed                            | Not Required                                |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm                                  |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm                                      |
| В          | Sanitary/Sewage/Water Supply System   |   |   |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required                                |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required                                |
| 3          | Sink Stainless steel (22)   | 1                                       | 1   |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required                                |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required                                |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required                                |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1   |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required                                |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required                                |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required                                |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required                                |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m                                       |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required                                |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work  | Provisions/ Quantity     | Provisions/ Quantity as      |
|------|---|--------------------------|------------------------------|
| 0.   | (TS Sr. No.)  | as per TS Estimate       | per present site requirement |
| A    | Civil works   |                          |                              |
| 1    | Internal Wall Distemper (1,41,42)   | 507.16 sqm               | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)           | 30 sqm                       |
| 3    | Wall Plaster (3,39)   | 60.14 sqm                | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                    | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                    | V-04,D-01                    |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed             | Not Required                 |
| 7    | PCC Apron (7,8,12)  | Not Proposed             | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed             | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)   | 101.89 sqm               | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)   | Proposed                 | 02                           |
| 12   | UPVC Vent (26)  | 4                        | 4                            |
| 13   | External Wall Painting (1,43)   | 290.19 sqm               | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)   | 5.87 sqm(avg)            | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                 | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT | Dropped/Changed by MMMUT     |
| 17   | Anti Termite Treatment (53,54)  | Not Proposed             | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                 | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)   |                          |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed             | Not Required                 |
| 21   | Granite Kitchen top (35,36)   | Not Proposed             | Not Required                 |
| 22   | Painting D/W/V (32,34)  | 83.36 sqm                | 103.36 sqm                   |
| 23   | CC Approach Road (16)   | Not Proposed             | Required                     |
| 24   | Septic Tank   | Not Proposed             | Not Required                 |
| 25   | Soak Pit  | Not Proposed             | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm               | 148.50 sqm                   |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed             | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System   | 1                        |                              |
| 1    | WC Pan/Commode (17,18)  | Not Proposed             | 01                           |
| 2    | Wash Basin (21)   | Not Proposed             | Not Required                 |
| 3    | Sink Stainless steel (22)   | 1                        | 1                            |
| 4    | Jet for Commode S Steel (23)  | Not Proposed             | Not Required                 |
| 5    | PVC Connection pipe   | Not Proposed             | Not Required                 |
| 6    | PVC Waste pipe  | Not Proposed             | Not Required                 |
| 7    | CP Brass Bibcock long body (26)   | 1                        | 1                            |
| 8    | CP Brass Shower (27)  | Not Proposed             | Not Required                 |
| 9    | CP Brass Wall Mixer (28)  | Not Proposed             | Not Required                 |
| 10   | CP Brass Angle Valve (29)   | Not Proposed             | Not Required                 |
| 11   | CP Brass Basin Mixer (30)   | Not Proposed             | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)  | 5.5 m                    | 12 m                         |
| C1   | Electrification work/Rewiring   | Not Proposed             | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as         |
|------|--|-----------------------------|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site<br>requirement |
| A    | Civil works  |                             |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                       | V-04                            |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                      |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                | Not Required                    |
| 12   | UPVC Vent (26)   | 4                           | 4                               |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                       |
|      | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                        |
|      | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                       |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT        |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                    |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                        |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                                 |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                    |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                    |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                      |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                        |
| 24   | Septic Tank  | Not Proposed                | Not Required                    |
| 25   | Soak Pit   | Not Proposed                | Not Required                    |
| 23   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                      |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  |                             |                                 |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                    |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                    |
| 3    | Sink Stainless steel (22)  | 1                           | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                    |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   | requirement  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | V-02,D-01  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)  | 4                                       | 4  |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
| ,          | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)   |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 24         | Septic Tank   | Not Proposed                            | Not Required   |
| 25         | Soak Pit  | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work  | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|---|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)  | as per TS Estimate          | per present site requirement |
| A    | Civil works   |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)   | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)   | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                       | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                       | V-04,D-01                    |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)  | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                | 02                           |
| 12   | UPVC Vent (26)  | 4                           | 03                           |
| 13   | External Wall Painting (1,43)   | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)   | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                   | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                    | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                   | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 17   | Anti Termite Treatment (53,54)  | Not Proposed                | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                    | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)   | The South Contract of       |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                | Not Required                 |
| 21   | Granite Kitchen top (35,36)   | Not Proposed                | Not Required                 |
| 22   | Painting D/W/V (32,34)  | 83.36 sqm                   | 103.36 sqm                   |
| 23   | CC Approach Road (16)   | Not Proposed                | Required                     |
| 24   | Septic Tank   | Not Proposed                | Not Required                 |
| 25   | Soak Pit  | Not Proposed                | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System   |                             |                              |
| 1    | WC Pan/Commode (17,18)  | Not Proposed                | Not Required                 |
| 2    | Wash Basin (21)   | Not Proposed                | Not Required                 |
| 3    | Sink Stainless steel (22)   | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)  | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe   | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe  | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)   | 1                           | 1                            |
| 8    | CP Brass Shower (27)  | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)  | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)   | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)   | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)  | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring   | Not Proposed                | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             | , , , , ,                    |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                       | V-05, D-02, W-01             |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                | 02                           |
| 12   | UPVC Vent (26)   | 4                           | 4                            |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by<br>MMMUT  |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                 |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 24   | Septic Tank  | Not Proposed                | Not Required                 |
| 25   | Soak Pit   | Not Proposed                | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 24 . | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             |                              |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                 |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                 |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| Cl   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | V-04,D-01,W-02   |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)  | 4                                       | 4  |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
| ,          | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)   |   | Variation of the second                                    |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 24         | Septic Tank   | Not Proposed                            | Not Required   |
| 25         | Soak Pit  | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as         |
|------|--|-----------------------------|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site<br>requirement |
| A    | Civil works  |                             |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                       | V-02,W-01                       |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                      |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                | 02                              |
| 12   | UPVC Vent (26)   | 4                           | 4                               |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                       |
|      | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                        |
|      | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                       |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT        |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                    |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                        |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                                 |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                    |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                    |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                      |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                        |
| 24   | Septic Tank  | Not Proposed                | Not Required                    |
| 25   | Soak Pit   | Not Proposed                | Not Required                    |
| 23   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                      |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  |                             |                                 |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                    |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                    |
| 3    | Sink Stainless steel (22)  | 1                           | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                    |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | V-01,W-01  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | 02   |
| 12         | UPVC Vent (26)   | 4                                       | 6  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site |
|------------|---|---|---|
| ٠.         | (12 211101)   | as per 10 Bomare                        | requirement                                 |
| A          | Civil works   |   | ***   |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm                                  |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm                                      |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm                                   |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W1,D1                                       |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | V-06,                                       |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required                                |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required                                    |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required                                |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm                                  |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | 02  |
| 12         | UPVC Vent (26)  | 4                                       | 4   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm                                  |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm                                   |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm                                   |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm                                    |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm                                   |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                    |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required                                |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm                                    |
| 19         | Drain Courtyard (6,7,16,17)   |   |   |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required                                |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required                                |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm                                  |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required                                    |
| 24         | Septic Tank   | Not Proposed                            | Not Required                                |
| 25         | Soak Pit  | Not Proposed                            | Not Required                                |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm                                  |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm                                      |
| В          | Sanitary/Sewage/Water Supply System   |   |   |
| 1          | WC Pan/Commode (17,18)  | Proposed                                | 01  |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required                                |
| 3          | Sink Stainless steel (22)   | 1                                       | 1   |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required                                |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required                                |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required                                |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1   |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required                                |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required                                |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required                                |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required                                |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m                                       |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required                                |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|--|--|
| A          | Civil works   |  | 1  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                      | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                      | W1,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                               | Not Required   |
| 12         | UPVC Vent (26)  | 4  | 4  |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                                  | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                   | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                                  | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                               | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                   | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)   |  |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                               | Not Required   |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                               | Not Required   |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                                  | 103.36 sqm   |
| 23         | CC Approach Road (16)   | Not Proposed                               | Required   |
| 24         | Septic Tank   | Not Proposed                               | Not Required   |
| 25         | Soak Pit  | Not Proposed                               | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                                 | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |  |  |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)   | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (22)   | 1  | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1  | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as         |
|------|--|-----------------------------|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site<br>requirement |
| A    | Civil works  |                             |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm                    | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                       | 2 Nos D                         |
| 6    | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                      |
| 11   | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                | Not Required                    |
| 12   | UPVC Vent (26)   | 2                           | 2                               |
| 13   | External Wall Painting (1, 43)   | 290.19 sqm                  | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm                    | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                   | 26.28 sqm                       |
|      | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                    | 5.13 sqm                        |
|      | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                   | 24.18 sqm                       |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT        |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                    |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                        |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                                 |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                | Not Required                    |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                    |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                      |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                        |
| 24   | Septic Tank  | Not Proposed                | Not Required                    |
| 25   | Soak Pit   | Not Proposed                | Not Required                    |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                  | 148.50 sqm                      |
| 24   | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  |                             |                                 |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                    |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                    |
| 3    | Sink Stainless steel (22)  | 1                           | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                    |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm                    | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                       | Not Required                 |
| 6    | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                | Not Required                 |
| 12   | UPVC Vent (26)   | 2                           | 2                            |
| 13   | External Wall Painting (1, 43)   | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm                    | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                   | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                    | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                   | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                | Not Required                 |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 24   | Septic Tank  | Not Proposed                | Not Required                 |
| 25   | Soak Pit   | Not Proposed                | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 24   | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             |                              |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                 |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                 |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm                    | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                       | Not Required                 |
| 6    | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                | Not Required                 |
| 12   | UPVC Vent (26)   | 2                           | 2                            |
| 13   | External Wall Painting (1, 43)   | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm                    | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                   | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                    | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                   | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                | Not Required                 |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 24   | Septic Tank  | Not Proposed                | Not Required                 |
| 25   | Soak Pit   | Not Proposed                | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 24   | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             |                              |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                 |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                 |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| CI   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   | requirement  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm                                | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                                   | 3 Nos D/02 Nos W   |
| 6          | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)   | 2                                       | 2  |
| 13         | External Wall Painting (1, 43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm                                | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | i  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | <u> </u>   |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | Total Section                              |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm                                   | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                      | 07 Nos   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                                      | 01 Nos D   |
| 6          | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                               | Not Required   |
| 12         | UPVC Vent (26)   | 2  | 2  |
| 13         | External Wall Painting (1, 43)   | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm                                   | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                                  | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                                   | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                                  | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                               | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                   | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |  |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                               | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                               | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                                  | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                               | Required   |
| 24         | Septic Tank  | Not Proposed                               | Not Required   |
| 25         | Soak Pit   | Not Proposed                               | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                                 | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  | John Re Moss                               | HAT HELD IN  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (22)  | 1  | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                               | Not Required   |
| 7.         | CP Brass Bibcock long body (26)  | 1  | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm                                | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | 1 No W   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                  | W3,D1                                   | 04 No. V/02 No D                                     |
| 6          | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver. L/B, G toilet (25)   | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)   | 2                                       | 2  |
| 13         | External Wall Painting (1, 43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm                                | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)            | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                            | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                 | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                            | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                             |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                   | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra Item Approved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  | To a control from the                   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as per present site |
|------------|---|--|--|
| A          | Civil works   |  | requirement                              |
| ĺ          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                                 | 507.16 sqm                               |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm                                   | 30 sqm                                   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                                  | 60.14 sqm                                |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                      | W1,D1                                    |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                               | W3,D1                                      | 04-V,01-D, 07-W                          |
| 6          | PCC Flooring (8,12) ver L/B, Kitchen Guest Toilet                                   | Not Proposed                               | Not Required                             |
| 7          | PCC Apron (7,8,12)  | Not Proposed                               | Required                                 |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                               | Not Required                             |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                                 | 101.89 sqm                               |
| - 11       | PVC solid door shutter ver. L/B, G toilet (25)                                      | Not Proposed                               | Not Required                             |
| 12         | UPVC Vent (26)  | 2  | 2  |
| 13         | External Wall Painting (1, 43)  | 290.19 sqm                                 | 290.19 sqm                               |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm                                   | 17.87 sqm                                |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)         | 26.28 sqm                                  | 26.28 sqm                                |
|            | Water proofing with chemical coating on Guest toilet(46,48)                         | 5.13 sqm                                   | 5.13 sqm                                 |
|            | Water proofing with chemical coating on Garage (46,48)                              | 24.18 sqm                                  | 24.18 sqm                                |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                         | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                 |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                               | Not Required                             |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                   | 9.87 sqm                                 |
| 19         | Drain Courtyard (6,7,16,17)   |  |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                | Not Proposed                               | Not Required                             |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                               | Not Required                             |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                                  | 103.36 sqm                               |
| 23         | CC Approach Road (16)   | Not Proposed                               | Required                                 |
| 24         | Septic Tank   | Not Proposed                               | Not Required                             |
| 25         | Soak Pit  | Not Proposed                               | Not Required                             |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra Item Approved by MMMUT) | 148.50 sqm                                 | 148.50 sqm                               |
| 24         | Chemical Coating for wet surface (Extra Item Approved by MMMUT)                     | Not Proposed                               | 40 sqm                                   |
| В          | Sanitary/Sewage/Water Supply System   |  |  |
| 1          | WC Pan/Commode (17,18)  | Proposed                                   | 01                                       |
| 2          | Wash Basin (21)   | Not Proposed                               | Not Required                             |
| 3          | Sink Stainless steel (22)   | 1  | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                               | Not Required                             |
| 5          | PVC Connection pipe   | Not Proposed                               | Not Required                             |
| 6          | PVC Waste pipe  | Not Proposed                               | Not Required                             |
| 7          | CP Brass Bibcock long body (26)   | 1  | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                               | Not Required                             |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                               | Not Required                             |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                               | Not Required                             |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                               | Not Required                             |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                      | 5.5 m                                    |
| C1         | Electrification work/Rewiring   | Not Proposed                               | Not Required                             |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1                                       | . 1  |
| 2          | Wash Basin (21)  | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | . 1                                     | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | Not Proposed                 |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                       | W2,D1                        |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                           | 2                            |
| 12   | UPVC Vent (26)   | Not Proposed                | Not Proposed                 |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                    |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                     |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                    |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| 21   | Drain Courtyard (6,7,16,17)  |                             |                              |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                 |
| 23   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 25   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 26   | Septic Tank  | Not Proposed                | Not Required                 |
| 27   | Soak Pit   | Not Proposed                | Not Required                 |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                | Not Proposed                 |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             |                              |
| 1    | WC Pan/Commode (17,18)   | 1                           | 1                            |
| 2    | Wash Basin (21)  | Proposed                    | Required                     |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | 2                                       | 2  |
| 12         | UPVC Vent (26)  | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)   |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 26         | Septic Tank   | Not Proposed                            | Not Required   |
| 27         | Soak Pit  | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | 1                                       | 1  |
| 2          | Wash Basin (21)   | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|--|--|
| A          | Civil works   |  |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                      | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                                      | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | 2  | 2  |
| 12         | UPVC Vent (26)  | Not Proposed                               | Not Proposed   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                                  | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                   | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                                  | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                   | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)  | Not Proposed                               | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                   | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)   |  |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                               | Not Required   |
| 23         | Granite Kitchen top (35,36)   | Not Proposed                               | Not Required   |
| 24         | Painting D/W/V (32,34)  | 83.36 sqm                                  | 103.36 sqm   |
| 25         | CC Approach Road (16)   | Not Proposed                               | Required   |
| 26         | Septic Tank   | Not Proposed                               | Not Required   |
| 27         | Soak Pit  | Not Proposed                               | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | Not Proposed                               | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |  | 0.50 % (1.50   |
| 1          | WC Pan/Commode (17,18)  | 1  | - 1  |
| 2          | Wash Basin (21)   | Proposed                                   | Required   |
| 3          | Sink Stainless steel (22)   | -1   | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1  | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                               | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity   | Provisions/ Quantity as         |
|------|--|--|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate   | per present site<br>requirement |
| A    | Civil works  |  |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm   | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)   | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm  | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1  | Not Proposed                    |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1  | W2,D1                           |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed   | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed   | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed   | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm   | 101.89 sqm                      |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2  | 2                               |
| 12   | UPVC Vent (26)   | Not Proposed   | Not Proposed                    |
| 13   | External Wall Painting (1,43)  | 290.19 sqm   | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)  | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm  | 26.28 sqm                       |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm   | 5.13 sqm                        |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm  | 24.18 sqm                       |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT  | Dropped/Changed by MMMUT        |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed   | Not Required                    |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm   | 9.87 sqm                        |
| 21   | Drain Courtyard (6,7,16,17)  | W AND THE PARTY OF |                                 |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed   | Not Required                    |
| 23   | Granite Kitchen top (35,36)  | Not Proposed   | Not Required                    |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm  | 103.36 sqm                      |
| 25   | CC Approach Road (16)  | Not Proposed   | Required                        |
| 26   | Septic Tank  | Not Proposed   | Not Required                    |
| 27   | Soak Pit   | Not Proposed   | Not Required                    |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed   | Not Proposed                    |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed   | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  | State of the second  | and the same of the same of     |
| 1    | WC Pan/Commode (17,18)   | 1  | 1                               |
| 2    | Wash Basin (21)  | Proposed   | Required                        |
| 3    | Sink Stainless steel (22)  | 1  | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed   | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed   | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed   | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | 1  | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed   | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed   | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed   | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed   | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m  | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed   | Not Required                    |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity     | Provisions/ Quantity as                |
|------|--|--------------------------|--|
| 0.   | (TS Sr. No.)   | as per TS Estimate       | per present site<br>requirement        |
| A    | Civil works  |                          | requirement                            |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm               | 507.16 sqm                             |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)           | 30 sqm                                 |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                | 60.14 sqm                              |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                    | Not Proposed                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                    | W2,D1                                  |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed             | Not Required                           |
| 7    | PCC Apron (7,8,12)   | Not Proposed             | Required                               |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed             | Not Required                           |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm               | 101.89 sqm                             |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                        | 2                                      |
| 12   | UPVC Vent (26)   | Not Proposed             | Not Proposed                           |
| 13   | External Wall Painting (1,43)  | 290.19 sqm               | 290.19 sqm                             |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)            | 17.87 sqm                              |
| 15   | Water proofing with chemical coating on Front Ver &                                | 26.28 sqm                | 26.28 sqm                              |
| 107  | Portico rooftop (46,48)  |                          | ************************************** |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                 | 5.13 sqm                               |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                | 24.18 sqm                              |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT | Dropped/Changed by MMMUT               |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed             | Not Required                           |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                 | 9.87 sqm                               |
| 21   | Drain Courtyard (6,7,16,17)  |                          |  |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed             | Not Required                           |
| 23   | Granite Kitchen top (35,36)  | Not Proposed             | Not Required                           |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm                | 103.36 sqm                             |
| 25   | CC Approach Road (16)  | Not Proposed             | Required                               |
| 26   | Septic Tank  | Not Proposed             | Not Required                           |
| 27   | Soak Pit   | Not Proposed             | Not Required                           |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed             | Not Proposed                           |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed             | 40 sqm                                 |
| В    | Sanitary/Sewage/Water Supply System  |                          |  |
| 1    | WC Pan/Commode (17,18)   | 1                        | 1                                      |
| 2    | Wash Basin (21)  | Proposed                 | Required                               |
| 3    | Sink Stainless steel (22)  | 1                        | 1                                      |
| 4    | Jet for Commode S Steel (23)   | Not Proposed             | Not Required                           |
| 5    | PVC Connection pipe  | Not Proposed             | Not Required                           |
| 6    | PVC Waste pipe   | Not Proposed             | Not Required                           |
| 7    | CP Brass Bibcock long body (26)  | 1                        | 1                                      |
| 8    | CP Brass Shower (27)   | Not Proposed             | Not Required                           |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed             | Not Required                           |
| 10   | CP Brass Angle Valve (29)  | Not Proposed             | Not Required                           |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed             | Not Required                           |
|      |  | 5.5 m                    |  |
| 12   | PVC Rain Water pipe (31,32,33)   | 1 33m I                  | 5.5 m                                  |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   | requirement  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                             |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1                                       | 1  |
| 2          | Wash Basin (21)  | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  | - Audinomont   |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                      | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                      | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2  | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                               | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                                  | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                   | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                                  | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                               | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                   | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |  |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                               | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                               | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                                  | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                               | Required   |
| 26         | Septic Tank  | Not Proposed                               | Not Required   |
| 27         | Soak Pit   | Not Proposed                               | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                               | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |  | 7.3  |
| 1          | WC Pan/Commode (17,18)   | 1  | 1  |
| 2          | Wash Basin (21)  | Proposed                                   | Required   |
| 3          | Sink Stainless steel (22)  | 1-1-                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1  | 1.00   |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-1                                     | 1  |
| 2          | Wash Basin (21)  | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1 /  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             | requirement                  |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | Not Proposed                 |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                       | W2,D1                        |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                           | 2                            |
| 12   | UPVC Vent (26)   | Not Proposed                | Not Proposed                 |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                    |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                     |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                    |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| . 21 | Drain Courtyard (6,7,16,17)  | En Tropico                  |                              |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                 |
| 23   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 25   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 26   | Septic Tank  | Not Proposed                | Not Required                 |
| 27   | Soak Pit   | Not Proposed                | Not Required                 |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                | Not Proposed                 |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             | na vedici na ma              |
| 1    | WC Pan/Commode (17,18)   | 1                           | 1                            |
| 2    | Wash Basin (21)  | Proposed                    | Required                     |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|--|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site requirement |
| A    | Civil works  |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                       | Not Proposed                 |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                       | W2,D1                        |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                           | 2                            |
| 12   | UPVC Vent (26)   | Not Proposed                | Not Proposed                 |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                    |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                     |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                    |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                 |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                     |
| 21   | Drain Courtyard (6,7,16,17)  |                             |                              |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                 |
| 23   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                 |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                   |
| 25   | CC Approach Road (16)  | Not Proposed                | Required                     |
| 26   | Septic Tank  | Not Proposed                | Not Required                 |
| 27   | Soak Pit   | Not Proposed                | Not Required                 |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                             |                              |
| 1    | WC Pan/Commode (17,18)   | 1                           | 1 .                          |
| 2    | Wash Basin (21)  | Proposed                    | Required                     |
| 3    | Sink Stainless steel (22)  | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                           | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                 |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity     | Provisions/ Quantity as      |
|------|--|--------------------------|------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate       | per present site requirement |
| A    | Civil works  |                          |                              |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm               | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)           | 30 sqm                       |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                    | Not Proposed                 |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                    | W2,D1                        |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed             | Not Required                 |
| 7    | PCC Apron (7,8,12)   | Not Proposed             | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed             | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm               | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                        | 2                            |
| 12   | UPVC Vent (26)   | Not Proposed             | Not Proposed                 |
| 13   | External Wall Painting (1,43)  | 290.19 sqm               | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)            | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                | 26.28 sqm                    |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                 | 5.13 sqm                     |
| 17   | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                | 24.18 sqm                    |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT | Dropped/Changed by MMMUT     |
| 19   | Anti Termite Treatment (53,54)   | Not Proposed             | Not Required                 |
| 20   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                 | 9.87 sqm                     |
| 21   | Drain Courtyard (6,7,16,17)  |                          |                              |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed             | Not Required                 |
| 23   | Granite Kitchen top (35,36)  | Not Proposed             | Not Required                 |
| 24   | Painting D/W/V (32,34)   | 83.36 sqm                | 103.36 sqm                   |
| 25   | CC Approach Road (16)  | Not Proposed             | Required                     |
| 26   | Septic Tank  | Not Proposed             | Not Required                 |
| 27   | Soak Pit   | Not Proposed             | Not Required                 |
| 28   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm               | 148.50 sqm                   |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed             | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System  |                          |                              |
| 1    | WC Pan/Commode (17,18)   | 1                        | 1                            |
| 2    | Wash Basin (21)  | Proposed                 | Required                     |
| 3    | Sink Stainless steel (22)  | 1                        | 1                            |
| 4    | Jet for Commode S Steel (23)   | Not Proposed             | Not Required                 |
| 5    | PVC Connection pipe  | Not Proposed             | Not Required                 |
| 6    | PVC Waste pipe   | Not Proposed             | Not Required                 |
| 7    | CP Brass Bibcock long body (26)  | 1                        | 1                            |
| 8    | CP Brass Shower (27)   | Not Proposed             | Not Required                 |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed             | Not Required                 |
| 10   | CP Brass Angle Valve (29)  | Not Proposed             | Not Required                 |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed             | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                    | 5.5 m                        |
| C1   | Electrification work/Rewiring  | Not Proposed             | Not Required                 |

J.E.,UPRNSS

### Gha/IV/1

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1                                       | 1  |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | i  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

### Gha/IV/2

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | 2                                       | 2  |
| 12         | UPVC Vent (26)  | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)   |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 26         | Septic Tank   | Not Proposed                            | Not Required   |
| 27         | Soak Pit  | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | 1                                       | 1  |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                      | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                      | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2  | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                               | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                                  | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                   | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                                  | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                               | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                   | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |  |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                               | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                               | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                                  | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                               | Required   |
| 26         | Septic Tank  | Not Proposed                               | Not Required   |
| 27         | Soak Pit   | Not Proposed                               | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                                 | 148.50 sqm   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |  |  |
| 1          | WC Pan/Commode (17,18)   | 1  | 1  |
| 2          | Wash Basin (21)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (22)  | 1  | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1  | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                               | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1                                       | 1  |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | 2                                       | 2  |
| 12         | UPVC Vent (26)  | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)   | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 26         | Septic Tank   | Not Proposed                            | Not Required   |
| 27         | Soak Pit  | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | 1                                       | 1  |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as per present site |
|------------|--|--|--|
|            |  |  | requirement                              |
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                                 | 507.16 sqm                               |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                             | 30 sqm                                   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                                  | 60.14 sqm                                |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                      | Not Proposed                             |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                      | W2,D1                                    |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                               | Not Required                             |
| 7          | PCC Apron (7,8,12)   | Not Proposed                               | Required                                 |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                               | Not Required                             |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                                 | 101.89 sqm                               |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2  | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                               | Not Proposed                             |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                                 | 290.19 sqm                               |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                              | 17.87 sqm                                |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                                  | 26.28 sqm                                |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                   | 5.13 sqm                                 |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                                  | 24.18 sqm                                |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                   | Dropped/Changed by MMMUT                 |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                               | Not Required                             |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                   | 9.87 sqm                                 |
| 21         | Drain Courtyard (6,7,16,17)  |  |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                               | Not Required                             |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                               | Not Required                             |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                                  | 103.36 sqm                               |
| 25         | CC Approach Road (16)  | Not Proposed                               | Required                                 |
| 26         | Septic Tank  | Not Proposed                               | Not Required                             |
| 27         | Soak Pit   | Not Proposed                               | Not Required                             |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                                 | 148.50 sqm                               |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                               | 40 sqm                                   |
| В          | Sanitary/Sewage/Water Supply System  |  |  |
| 1          | WC Pan/Commode (17,18)   | 1  | 1 .                                      |
| 2          | Wash Basin (21)  | Not Proposed                               | Not Required                             |
| 3          | Sink Stainless steel (22)  | 1  | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                               | Not Required                             |
| 5          | PVC Connection pipe  | Not Proposed                               | Not Required                             |
| 6          | PVC Waste pipe   | Not Proposed                               | Not Required                             |
| 7          | CP Brass Bibcock long body (26)  | 1  | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required                             |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                               | Not Required                             |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                               | Not Required                             |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                               | Not Required                             |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                      | 5.5 m                                    |
| C1         | Electrification work/Rewiring  | Not Proposed                               | Not Required                             |

J.E., UPRNSS

### Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|--|--|
| A          | Civil works   |  | requirement  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                      | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                                      | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | 2  | 2  |
| 12         | UPVC Vent (26)  | Not Proposed                               | Not Proposed   |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                                  | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                   | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                                  | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)  | Not Proposed                               | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                   | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)   | Low War City and a second                  | to Additional territory                                    |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                               | Not Required   |
| 23         | Granite Kitchen top (35,36)   | Not Proposed                               | Not Required   |
| 24         | Painting D/W/V (32,34)  | 83.36 sqm                                  | 103.36 sqm   |
| 25         | CC Approach Road (16)   | Not Proposed                               | Required   |
| 26         | Septic Tank   | Not Proposed                               | Not Required   |
| 27         | Soak Pit  | Not Proposed                               | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | Not Proposed                               | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   | Company And Aller A.                       | marries request dispersión in                              |
| 1          | WC Pan/Commode (17,18)  | $\mathbf{i}$                               | 1 2 2  |
| 2          | Wash Basin (21)   | Proposed                                   | Required   |
| 3          | Sink Stainless steel (22)   | Mail Town                                  | 14,85  |
| 4          | Jet for Commode S Steel (23)  | Proposed                                   | Required   |
| 5          | PVC Connection pipe   | Proposed                                   | Required   |
| 6          | PVC Waste pipe  | Proposed                                   | Required   |
| 7          | CP Brass Bibcock long body (26)   | 25.5 T (46.5)                              | 1.   |
| 8          | CP Brass Shower (27)  | Proposed                                   | Required   |
| 9          | CP Brass Wall Mixer (28)  | Proposed                                   | Required   |
| 10         | CP Brass Angle Valve (29)   | Proposed                                   | Required   |
| 11         | CP Brass Basin Mixer (30)   | Proposed                                   | Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                               | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   | 76.7 (1946)  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | 1                                       | 1  |
| 2          | Wash Basin (21)  | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | Not Proposed   |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W2,D1                                   | W2,D1  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | 2                                       | 2  |
| 12         | UPVC Vent (26)   | Not Proposed                            | Not Proposed   |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
| 16         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
| 17         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 18         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 19         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 20         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 21         | Drain Courtyard (6,7,16,17)  |   |  |
| 22         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 23         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 24         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 25         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 26         | Septic Tank  | Not Proposed                            | Not Required   |
| 27         | Soak Pit   | Not Proposed                            | Not Required   |
| 28         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 29         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   | K4   |
| 1          | WC Pan/Commode (17,18)   | . 1                                     | 1  |
| 2          | Wash Basin (21)  | Proposed                                | Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work  | Provisions/ Quantity     | Provisions/ Quantity as      |
|------|---|--------------------------|------------------------------|
| 0.   | (TS Sr. No.)  | as per TS Estimate       | per present site requirement |
| A    | Civil works   |                          |                              |
| 1    | Internal Wall Distemper (1,41,42)   | 507.16 sqm               | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)           | 30 sqm                       |
| 3    | Wall Plaster (3,39)   | 60.14 sqm                | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                    | Not Proposed                 |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W2,D1                    | W2,D1                        |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed             | Not Required                 |
| 7    | PCC Apron (7,8,12)  | Not Proposed             | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed             | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)   | 101.89 sqm               | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)   | 2                        | 2                            |
| 12   | UPVC Vent (26)  | Not Proposed             | Not Proposed                 |
| 13   | External Wall Painting (1,43)   | 290.19 sqm               | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)   | 5.87 sqm(avg)            | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                | 26.28 sqm                    |
| 16   | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                 | 5.13 sqm                     |
| 17   | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                | 24.18 sqm                    |
| 18   | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT | Dropped/Changed by MMMUT     |
| 19   | Anti Termite Treatment (53,54)  | Not Proposed             | Not Required                 |
| 20   | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                 | 9.87 sqm                     |
| 21   | Drain Courtyard (6,7,16,17)   |                          |                              |
| 22   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed             | Not Required                 |
| 23   | Granite Kitchen top (35,36)   | Not Proposed             | Not Required                 |
| 24   | Painting D/W/V (32,34)  | 83.36 sqm                | 103.36 sqm                   |
| 25   | CC Approach Road (16)   | Not Proposed             | Required                     |
| 26   | Septic Tank   | Not Proposed             | Not Required                 |
| 27   | Soak Pit  | Not Proposed             | Not Required                 |
| 28   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | Not Proposed             | Not Proposed                 |
| 29   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed             | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System   |                          |                              |
| 1    | WC Pan/Commode (17,18)  | 1                        | 1                            |
| 2    | Wash Basin (21)   | Proposed                 | Required                     |
| 3    | Sink Stainless steel (22)   | 1                        | 1                            |
| 4    | Jet for Commode S Steel (23)  | Not Proposed             | Not Required                 |
| 5    | PVC Connection pipe   | Not Proposed             | Not Required                 |
| 6    | PVC Waste pipe  | Not Proposed             | Not Required                 |
| 7    | CP Brass Bibcock long body (26)   | 1                        | 1,                           |
| 8    | CP Brass Shower (27)  | Not Proposed             | Not Required                 |
| 9    | CP Brass Wall Mixer (28)  | Not Proposed             | Not Required                 |
| 10   | CP Brass Angle Valve (29)   | Not Proposed             | Not Required                 |
| 11   | CP Brass Basin Mixer (30)   | Not Proposed             | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)  | 5.5 m                    | 5,5 m                        |
| C1   | Electrification work/Rewiring   | Not Proposed             | Not Required                 |

J.E.,UPRNSS

# Chh, AA/IV/3

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate   | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | The state of the s |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm   | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)   | 45 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm  | 130.00 sqm   |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1  | W4,D4, V-04  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1  | D-04,W-04,V-04   |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed   | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed   | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed   | Not Required   |
| 9          | Vitrified Tile Floor (13,15,52)  | 101.89 sqm   | 101.89 sqm   |
| 10         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed   | Not Required   |
| 11         | UPVC Vent (26)   | 4  | 2  |
| 12         | External Wall Painting (1,43)  | 290.19 sqm   | 290.19 sqm   |
| 13         | Mosquito Jali (44,45)  | 5.87 sqm(avg)  | 17.87 sqm  |
| 14         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm  | 26.28 sqm  |
| 15         | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm   | 5.13 sqm   |
| 16         | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm  | 24.18 sqm  |
| 17         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT  | Dropped/Changed by MMMUT                                   |
| 18         | Anti Termite Treatment (53,54)   | Not Proposed   | Not Required   |
| 19         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm   | 9.87 sqm   |
| 20         | Drain Courtyard (6,7,16,17)  |  |  |
| 21         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed   | Not Required   |
| 22         | Granite Kitchen top (35,36)  | Not Proposed   | Not Required   |
| 23         | Painting D/W/V (32,34)   | 83.36 sqm  | 103.36 sqm   |
| 24         | CC Approach Road (16)  | Not Proposed   | Required   |
| 25         | Septic Tank  | Not Proposed   | Not Required   |
| 26         | Soak Pit   | Not Proposed   | Not Required   |
| 27         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm   | 148.50 sqm   |
| 28         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed   | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  | and and a serious A  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed   | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed   | Not Required   |
| 3          | Sink Stainless steel (22)  | i i I  | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed   | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed   | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed   | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | Sagal service  | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed   | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed   | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed   | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed   | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m  | 5.5 m  |
| C1 ·       | Electrification work/Rewiring  | Not Proposed   | Not Required   |

# Chh, AA/IV/4

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 45 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 130.00 sqm   |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                                   | W4,D4, V-04  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | D-04,W-04,V-04   |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 9          | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 10         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | Not Required   |
| 11         | UPVC Vent (26)  | 4                                       | 2  |
| 12         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 13         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 14         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
| 15         | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
| 16         | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 17         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 18         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 19         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 20         | Drain Courtyard (6,7,16,17)   | was in his sale                         | s to produce and   |
| 21         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 22         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 23         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 24         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 25         | Septic Tank   | Not Proposed                            | Not Required   |
| 26         | Soak Pit  | Not Proposed                            | Not Required   |
| 27         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 28         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   | The constraint of the constraint of     | A service of the service of                                |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   |   |  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1.3.2 <b>4</b> Subar                    | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                      |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E., UPRNSS

A.E., UPRNSS

gradient began and

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work  | Provisions/ Quantity        | Provisions/ Quantity as      |
|------|---|-----------------------------|------------------------------|
| 0.   | (TS Sr. No.)  | as per TS Estimate          | per present site requirement |
| A    | Civil works   |                             |                              |
| 1    | Internal Wall Distemper (1,41,42)   | 507.16 sqm                  | 507.16 sqm                   |
| 2    | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)              | 30 sqm                       |
| 3    | Wall Plaster (3,39)   | 60.14 sqm                   | 60.14 sqm                    |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)   | W1,D1                       | W1,D1                        |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                       | D-01, W-04                   |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                | Not Required                 |
| 7    | PCC Apron (7,8,12)  | Not Proposed                | Required                     |
| 8    | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                | Not Required                 |
| 10   | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                  | 101.89 sqm                   |
| 11   | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                | 2                            |
| 12   | UPVC Vent (26)  | 4                           | 4                            |
| 13   | External Wall Painting (1,43)   | 290.19 sqm                  | 290.19 sqm                   |
| 14   | Mosquito Jali (44,45)   | 5.87 sqm(avg)               | 17.87 sqm                    |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                   | 26.28 sqm                    |
|      | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                    | 5.13 sqm                     |
|      | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                   | 24.18 sqm                    |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT     |
| 17   | Anti Termite Treatment (53,54)  | Not Proposed                | Not Required                 |
| 18   | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                    | 9.87 sqm                     |
| 19   | Drain Courtyard (6,7,16,17)   | The second                  |                              |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                | Not Required                 |
| 21   | Granite Kitchen top (35,36)   | Not Proposed                | Not Required                 |
| 22.  | Painting D/W/V (32,34)  | 83.36 sqm                   | 103.36 sqm                   |
| 23   | CC Approach Road (16)   | Not Proposed                | Required                     |
| 24   | Septic Tank   | Not Proposed                | Not Required                 |
| 25   | Soak Pit  | Not Proposed                | Not Required                 |
| 23   | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                  | 148.50 sqm                   |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                | 40 sqm                       |
| В    | Sanitary/Sewage/Water Supply System   |                             |                              |
| 1    | WC Pan/Commode (17,18)  | Not Proposed                | Not Required                 |
| 2    | Wash Basin (21)   | Not Proposed                | 1                            |
| 3    | Sink Stainless steel (22)   | 1                           | 1                            |
| 4    | Jet for Commode S Steel (23)  | Not Proposed                | Not Required                 |
| 5    | PVC Connection pipe   | Not Proposed                | Not Required                 |
| 6    | PVC Waste pipe  | Not Proposed                | Not Required                 |
| 7    | CP Brass Bibcock long body (26)   | 1                           | 2                            |
| 8    | CP Brass Shower (27)  | Not Proposed                | Not Required                 |
| 9    | CP Brass Wall Mixer (28)  | Not Proposed                | 1                            |
| 10   | CP Brass Angle Valve (29)   | Not Proposed                | Not Required                 |
| 11   | CP Brass Basin Mixer (30)   | Not Proposed                | Not Required                 |
| 12   | PVC Rain Water pipe (31,32,33)  | 5.5 m                       | 5.5 m                        |
| C1   | Electrification work/Rewiring   | Not Proposed                | Not Required                 |



J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                                 | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                             | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                                  | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                      | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                      | D-01,01-W  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                               | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                               | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                               | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                                 | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                               | Not Required   |
| 12         | UPVC Vent (26)   | 4  | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                                 | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                              | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                                  | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                   | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                                  | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                               | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                   | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |  | 7,0,7,0,4,1  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                               | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                               | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                                  | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                               | Required   |
| 24         | Septic Tank  | Not Proposed                               | Not Required   |
| 25         | Soak Pit   | Not Proposed                               | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                                 | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                               | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (22)  | 1  | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1  | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                      | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   | requirement  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | D-01,W-02  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | Not Required   |
| 12         | UPVC Vent (26)   | 4                                       | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N     | Name of Items/work   | Provisions/ Quantity         | Provisions/ Quantity as  |
|----------|--|------------------------------|--------------------------|
| 0.       | (TS Sr. No.)   | as per TS Estimate           | per present site         |
| A        | Civil works  |                              | requirement              |
| <u>A</u> | Internal Wall Distemper (1,41,42)  | 507.16 agm                   | 507.16 acm               |
| 2        | Ceiling Plaster (2,40)   | 507.16 sqm<br>7.97 sqm(avg.) | 507.16 sqm<br>30 sqm     |
| 3        | Wall Plaster (3,39)  | 60.14 sqm                    | 60.14 sqm                |
| 4        | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                        | W1,D1                    |
| 5        | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                        | D-02,                    |
| 6        | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                 | Not Required             |
| 7        | PCC Apron (7,8,12)   | Not Proposed                 | Required                 |
| 8        | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                 | Not Required             |
| 10       | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                   | 101.89 sqm               |
| 11       | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                 | 2                        |
| 12       | UPVC Vent (26)   | 4                            | 2                        |
| 13       | External Wall Painting (1,43)  | 290.19 sqm                   | 290.19 sqm               |
| 14       | Mosquito Jali (44,45)  | 5.87 sqm(avg)                | 17.87 sqm                |
| 15       | Water proofing with chemical coating on Front Ver &                                | 26.28 sqm                    | 26.28 sqm                |
|          | Portico rooftop (46,48)  | 20.20 5411                   | 20.20 Sqm                |
|          | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                     | 5.13 sqm                 |
|          | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                    | 24.18 sqm                |
| 16       | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT  | Dropped/Changed by MMMUT |
| 17       | Anti Termite Treatment (53,54)   | Not Proposed                 | Not Required             |
| 18       | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                     | 9.87 sqm                 |
| 19       | Drain Courtyard (6,7,16,17)  |                              |                          |
| 20       | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                 | Not Required             |
| 21       | Granite Kitchen top (35,36)  | Not Proposed                 | Not Required             |
| 22       | Painting D/W/V (32,34)   | 83.36 sqm                    | 103.36 sqm               |
| 23       | CC Approach Road (16)  | Not Proposed                 | Required                 |
| 24       | Septic Tank  | Not Proposed                 | Not Required             |
| 25       | Soak Pit   | Not Proposed                 | Not Required             |
| 23       | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                   | 148.50 sqm               |
| 24       | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                 | 40 sqm                   |
| В        | Sanitary/Sewage/Water Supply System  | 1                            | 3, 3, 1                  |
| 1        | WC Pan/Commode (17,18)   | Not Proposed                 | Not Required             |
| 2        | Wash Basin (21)  | Not Proposed                 | Not Required             |
| 3        | Sink Stainless steel (22)  | 11                           | 1                        |
| 4        | Jet for Commode S Steel (23)   | Not Proposed                 | Not Required             |
| 5        | PVC Connection pipe  | Not Proposed                 | Not Required             |
| 6        | PVC Waste pipe   | Not Proposed                 | Not Required             |
| 7        | CP Brass Bibcock long body (26)  | 1                            | 1                        |
| 8        | CP Brass Shower (27)   | Not Proposed                 | Not Required             |
| 9        | CP Brass Wall Mixer (28)   | Not Proposed                 | Not Required             |
| 10       | CP Brass Angle Valve (29)  | Not Proposed                 | Not Required             |
| 11       | CP Brass Basin Mixer (30)  | Not Proposed                 | Not Required             |
| 12       | PVC Rain Water pipe (31,32,33)   | 5.5 m                        | 5.5 m                    |
| C1       | Electrification work/Rewiring  | Not Proposed                 | Not Required             |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity     | Provisions/ Quantity as         |
|------|--|--------------------------|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate       | per present site<br>requirement |
| A    | Civil works  | 1-2                      |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm               | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)           | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                    | W1,D1                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                    | D-02,                           |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed             | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed             | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed             | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm               | 101.89 sqm                      |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed             | 2                               |
| 12   | UPVC Vent (26)   | 4                        | 2                               |
| 13   | External Wall Painting (1,43)  | 290.19 sqm               | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)            | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                | 26.28 sqm                       |
|      | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                 | 5.13 sqm                        |
|      | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                | 24.18 sqm                       |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT | Dropped/Changed by MMMUT        |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed             | Not Required                    |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                 | 9.87 sqm                        |
| 19   | Drain Courtyard (6,7,16,17)  |                          |                                 |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed             | Not Required                    |
| 21   | Granite Kitchen top (35,36)  | Not Proposed             | Not Required                    |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                | 103.36 sqm                      |
| 23   | CC Approach Road (16)  | Not Proposed             | Required                        |
| 24   | Septic Tank  | Not Proposed             | Not Required                    |
| 25   | Soak Pit   | Not Proposed             | Not Required                    |
| 23   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm               | 148.50 sqm                      |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed             | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  |                          |                                 |
| 1    | WC Pan/Commode (17,18)   | Not Proposed             | Not Required                    |
| 2    | Wash Basin (21)  | Not Proposed             | Not Required                    |
| 3    | Sink Stainless steel (22)  | . 1                      | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed             | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed             | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed             | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | 1                        | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed             | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed             | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed             | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed             | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                    | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed             | Not Required                    |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | D-02,  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)   | 4                                       | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W1,D1                                   | W1,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | D-02,  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)   | 4                                       | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1 2 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site |
|------------|---|---|--|
| A          | Civil works   |   | requirement                              |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm                               |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm                                   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm                                |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W5,D1                                   | W5,D1                                    |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | D-02,                                    |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required                             |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required                                 |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed  Not Proposed              | Not Required                             |
|            |   | 101.89 sqm                              |  |
| 10         | Vitrified Tile Floor (13,15,52) PVC solid door shutter ver L/B, G toilet (25)         |   | 101.89 sqm                               |
| 11         |   | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)  | 4                                       | 2  |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm                               |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm                                |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm                                |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm                                 |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm                                |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                 |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required                             |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm                                 |
| 19         | Drain Courtyard (6,7,16,17)   |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required                             |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required                             |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm                               |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required                                 |
| 24         | Septic Tank   | Not Proposed                            | Not Required                             |
| 25         | Soak Pit  | Not Proposed                            | Not Required                             |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed                             |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm                                   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required                             |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required                             |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required                             |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required                             |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required                             |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required                             |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required                             |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required                             |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required                             |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m                                    |
| C1         | Electrification work/Rewiring   | Not Proposed                            | Not Required                             |



J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W5,D1                                   | W5,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | D-02,  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)   | 4                                       | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                            | Not Proposed   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N | Name of Items/work   | Provisions/ Quantity        | Provisions/ Quantity as         |
|------|--|-----------------------------|---------------------------------|
| 0.   | (TS Sr. No.)   | as per TS Estimate          | per present site<br>requirement |
| A    | Civil works  |                             |                                 |
| 1    | Internal Wall Distemper (1,41,42)  | 507.16 sqm                  | 507.16 sqm                      |
| 2    | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)              | 30 sqm                          |
| 3    | Wall Plaster (3,39)  | 60.14 sqm                   | 60.14 sqm                       |
| 4    | D/W/V Frame/Chaukhat (4,18,19,20)  | W5,D1                       | W5,D1                           |
| 5    | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                       | D-02,                           |
| 6    | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                | Not Required                    |
| 7    | PCC Apron (7,8,12)   | Not Proposed                | Required                        |
| 8    | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                | Not Required                    |
| 10   | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                  | 101.89 sqm                      |
| 11   | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                | 2                               |
| 12   | UPVC Vent (26)   | 4                           | 2                               |
| 13   | External Wall Painting (1,43)  | 290.19 sqm                  | 290.19 sqm                      |
| 14   | Mosquito Jali (44,45)  | 5.87 sqm(avg)               | 17.87 sqm                       |
| 15   | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                   | 26.28 sqm                       |
|      | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                    | 5.13 sqm                        |
|      | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                   | 24.18 sqm                       |
| 16   | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed<br>by MMMUT | Dropped/Changed by MMMUT        |
| 17   | Anti Termite Treatment (53,54)   | Not Proposed                | Not Required                    |
| 18   | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                    | 9.87 sqm                        |
| 19   | Drain Courtyard (6,7,16,17)  |                             |                                 |
| 20   | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                | Not Required                    |
| 21   | Granite Kitchen top (35,36)  | Not Proposed                | Not Required                    |
| 22   | Painting D/W/V (32,34)   | 83.36 sqm                   | 103.36 sqm                      |
| 23   | CC Approach Road (16)  | Not Proposed                | Required                        |
| 24   | Septic Tank  | Not Proposed                | Not Required                    |
| 25   | Soak Pit   | Not Proposed                | Not Required                    |
| 23   | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | Not Proposed                | Not Proposed                    |
| 24   | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                | 40 sqm                          |
| В    | Sanitary/Sewage/Water Supply System  |                             |                                 |
| 1    | WC Pan/Commode (17,18)   | Not Proposed                | Not Required                    |
| 2    | Wash Basin (21)  | Not Proposed                | Not Required                    |
| 3    | Sink Stainless steel (22)  | 1                           | 1                               |
| 4    | Jet for Commode S Steel (23)   | Not Proposed                | Not Required                    |
| 5    | PVC Connection pipe  | Not Proposed                | Not Required                    |
| 6    | PVC Waste pipe   | Not Proposed                | Not Required                    |
| 7    | CP Brass Bibcock long body (26)  | - 1                         | 1                               |
| 8    | CP Brass Shower (27)   | Not Proposed                | Not Required                    |
| 9    | CP Brass Wall Mixer (28)   | Not Proposed                | Not Required                    |
| 10   | CP Brass Angle Valve (29)  | Not Proposed                | Not Required                    |
| 11   | CP Brass Basin Mixer (30)  | Not Proposed                | Not Required                    |
| 12   | PVC Rain Water pipe (31,32,33)   | 5.5 m                       | 5.5 m                           |
| C1   | Electrification work/Rewiring  | Not Proposed                | Not Required                    |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)   | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,41,42)  | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)   | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)  | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)  | W5,D1                                   | W5,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                              | W1,D1                                   | D-02,  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                   | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)   | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)   | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)  | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)                                      | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)   | - 4                                     | 2  |
| 13         | External Wall Painting (1,43)  | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)  | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)        | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                        | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                             | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                        | Dropped/Changed by MMMUT                | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)   | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)  | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)  |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                               | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)  | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)   | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)  | Not Proposed                            | Required   |
| 24         | Septic Tank  | Not Proposed                            | Not Required   |
| 25         | Soak Pit   | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc (Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                     | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System  |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | Not Proposed                            | Not Required   |
| .3         | Sink Stainless steel (22)  | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)  | 1                                       | 1  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)   | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)  | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)  | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)   | 5.5 m                                   | 5.5 m  |
| C1         | Electrification work/Rewiring  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)  | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|---|---|--|
| A          | Civil works   |   |  |
| 1          | Internal Wall Distemper (1,41,42)   | 507.16 sqm                              | 507.16 sqm   |
| 2          | Ceiling Plaster (2,40)  | 7.97 sqm(avg.)                          | 30 sqm   |
| 3          | Wall Plaster (3,39)   | 60.14 sqm                               | 60.14 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,18,19,20)   | W5,D1                                   | W5,D1  |
| 5          | D/W/V shutter/Palla (5,21,22,23,24,27,28,29,30,31,33)                                 | W1,D1                                   | D-02,  |
| 6          | PCC Flooring (8,12)ver L/B, Kitchen Guest Toilet                                      | Not Proposed                            | Not Required   |
| 7          | PCC Apron (7,8,12)  | Not Proposed                            | Required   |
| 8          | RCC Lintel Beam and chajja (9,10,11)  | Not Proposed                            | Not Required   |
| 10         | Vitrified Tile Floor (13,15,52)   | 101.89 sqm                              | 101.89 sqm   |
| 11         | PVC solid door shutter ver L/B, G toilet (25)   | Not Proposed                            | 2  |
| 12         | UPVC Vent (26)  | 4                                       | 2  |
| 13         | External Wall Painting (1,43)   | 290.19 sqm                              | 290.19 sqm   |
| 14         | Mosquito Jali (44,45)   | 5.87 sqm(avg)                           | 17.87 sqm  |
| 15         | Water proofing with chemical coating on Front Ver & Portico rooftop (46,48)           | 26.28 sqm                               | 26.28 sqm  |
|            | Water proofing with chemical coating on Guest toilet(46,48)                           | 5.13 sqm                                | 5.13 sqm   |
|            | Water proofing with chemical coating on Garage (46,48)                                | 24.18 sqm                               | 24.18 sqm  |
| 16         | Water proofing with APP membrane on roofs of rooms etc (49)                           | Dropped/Changed<br>by MMMUT             | Dropped/Changed by MMMUT                                   |
| 17         | Anti Termite Treatment (53,54)  | Not Proposed                            | Not Required   |
| 18         | Kota Stone Flooring (12,14,50,51)   | 9.87 sqm                                | 9.87 sqm   |
| 19         | Drain Courtyard (6,7,16,17)   |   |  |
| 20         | Ceramic Tile, Wall/Floor, L/B, Kitchen (12,14,37,38)                                  | Not Proposed                            | Not Required   |
| 21         | Granite Kitchen top (35,36)   | Not Proposed                            | Not Required   |
| 22         | Painting D/W/V (32,34)  | 83.36 sqm                               | 103.36 sqm   |
| 23         | CC Approach Road (16)   | Not Proposed                            | Required   |
| 24         | Septic Tank   | Not Proposed                            | Not Required   |
| 25         | Soak Pit  | Not Proposed                            | Not Required   |
| 23         | Water proofing with Brick Coba on roofs of rooms etc<br>(Extra ItemApproved by MMMUT) | 148.50 sqm                              | 148.50 sqm   |
| 24         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT)                        | Not Proposed                            | 40 sqm   |
| В          | Sanitary/Sewage/Water Supply System   |   |  |
| 1          | WC Pan/Commode (17,18)  | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)   | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (22)   | 1                                       | 1  |
| 4          | Jet for Commode S Steel (23)  | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe   | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe  | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (26)   | 1                                       | 1  |
| 8          | CP Brass Shower (27)  | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)  | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)   | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (30)   | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (31,32,33)  | 5.5 m                                   | 5.5 m  |
| 14         | Electrification work/Rewiring   | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not Proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-2N0., D-2 No.                         | W-2N0., D-2 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-1No., D-1No.                             | W-1No., D-1No.   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No.                                    | D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | E                                       | · ·  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                         | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(5,6,7)  |   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                   | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                   | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                   | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(5,6,7)  | 7 6 2 2 2                                  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | 1/24   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                         | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(5,6,7)  |   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   | 7.11   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                   | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                   | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                   | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                         | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(5,6,7)  |   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                   | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                   | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                   | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 15.00 sqm  |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 65.00 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | D-4 No., W-4No.                            | D-4 No., W-4No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-4 No., W-4No.                            | D-4 No., W-4No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2 No.                                      | 2 No.  |
| 11         | UPVC Vent (24)   | 2 No.                                      | 2 No.  |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | 1 No.                                      | 1 No   |
| 2          | Wash Basin (22)  | 1 No                                       | 1 No   |
| 3          | Sink Stainless steel (23)                                      | 1 No                                       | 1 No   |
| 4          | Jet for Commode S Steel (24)                                   | 1 No                                       | 1 No   |
| 5          | PVC Connection pipe(25)  | 1 No                                       | 1 No   |
| 6          | PVC Waste pipe(26)   | 1 No                                       | 1 No   |
| 7          | CP Brass Bibcock long body (27)                                | 1 No                                       | 1 No   |
| 8          | CP Brass Shower (28)   | 1 No                                       | 1 No   |
| 9          | CP Brass Wall Mixer (29)                                       | 1 No                                       | 1 No   |
| 10         | CP Brass Angle Valve (30)                                      | 1 No                                       | 1 No   |
| 11         | CP Brass Basin Mixer (31)                                      | 1 No                                       | 1 No   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 1 No                                       | 1 No   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 15.00 sqm  |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 65.00 sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | D-4 No., W-4No.                            | D-4 No., W-4No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-4 No., W-4No.                            | D-4 No., W-4No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2 No.                                      | 2 No.  |
| 11         | UPVC Vent (24)   | 2 No.                                      | 2 No.  |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | 1 No.                                      | 1 No   |
| 2          | Wash Basin (22)  | 1 No                                       | 1 No   |
| 3          | Sink Stainless steel (23)                                      | 1 No                                       | 1 No   |
| 4          | Jet for Commode S Steel (24)                                   | 1 No                                       | 1 No   |
| 5          | PVC Connection pipe(25)  | 1 No                                       | 1 No   |
| 6          | PVC Waste pipe(26)   | 1 No                                       | 1 No   |
| 7          | CP Brass Bibcock long body (27)                                | 1 No                                       | 1 No   |
| 8          | CP Brass Shower (28)   | 1 No                                       | 1 No   |
| 9          | CP Brass Wall Mixer (29)                                       | 1 No                                       | 1 No   |
| 10         | CP Brass Angle Valve (30)                                      | 1 No                                       | 1 No   |
| 11         | CP Brass Basin Mixer (31)                                      | 1 No                                       | 1 No   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 1 No                                       | 1 No   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate   | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm   | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)   | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)  | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed   | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.  | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed   | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32  | 29.32  |
| - 8        | RCC Lintel Beam and chajja (8)                                 | 0.17cum  | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed   | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed   | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm   | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)  | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed   | Not Required   |
| 15         | Court yard drain(5,6,7)  | and the state of t | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed   | Not Required   |
| 21         | Soak Pit   | Not proposed   | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed   | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed   | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed   | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.  | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed   | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.  | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed   | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.  | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed   | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed   | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed   | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed   | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed   | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed   | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | 7.40   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |
|            |  |  |  |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | A. 24 (1.1. S                              | 417.00   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., ÚPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(5,6,7)  |  | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | 74.3   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| . 1        | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                         | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(5,6,7)  |   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | 10 Print Print 1941                     | 3565   |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                   | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                   | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                   | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | D-1 No., W-1No.                            | D-1 No., W-1No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11.        | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(5,6,7)  | 1990 11 11 11                              | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | 15/  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 NO.                                      | 1 NO.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2 NO.                                      | 2 NO.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2 NO.                                      | 2 NO.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11 -       | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-4No.                                     | W-4No.   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-2N0.,D-2NO.                              | W-2NO,D-2NO.   |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | SECTION AND THE                            | The second second  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2–No.                                      | 2-No.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 1.7 m                                      | 6 m  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not Proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0.                                  | W-1NO  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                   | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 4-No.                                   | 4-No.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 1.7 m                                   | 6 m  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-3no., V-1 No.                         | W-3no., V-1 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-3N0., D-03 No.                        | W-3N0., D-03 No.   |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                   | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1-No.                                   | 1-No.  |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 1.7 m                                   | 6 m  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-4no., V-2 No.                         | W-4no., V-2 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-4N0., D-04 No.,<br>V-2                | W-4N0., D-04 No., V-2                                      |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                   | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not Proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-02 No.,<br>V-1                   | W-1N0., D-02 No., V-1                                      |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1No.                                       | 1No.   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Proposed                                   | Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|-----------|--|--|--|
| A         | Civil works  |  |  |
| 1         | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2         | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3         | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4         | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-2 no, V-1No.                             | W-2 no, V-1No.   |
| 5         | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.,<br>V-1                    | W-1N0., D-1 No., V-1                                       |
| 6         | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7         | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8         | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9         | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10        | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11        | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12        | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13        | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14        | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15        | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16        | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17        | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18        | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19        | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20        | Septic Tank  | Not proposed                               | Not Required   |
| 21        | Soak Pit   | Not proposed                               | Not Required   |
| 22        | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В         | Sanitary/Sewage/Water Supply System                            |  |  |
| 1         | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2         | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3         | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4         | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5         | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6         | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7         | CP Brass Bibcock long body (27)                                | 1No.                                       | 1No.   |
| 8         | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9         | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10        | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11        | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12        | PVC Rain Water pipe (32,33,34)                                 | 6Mtr.                                      | 6Mtr.  |
| C1        | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | D-2 No.                                    | D-2 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-3 No.,<br>V-1                    | W-1N0., D-3 No., V-1                                       |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | 1 No.                                      | 1 No.  |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1No.                                       | 1No.   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 6Mtr.                                      | 6Mtr.  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-1 No.,D-1 No.                            | W-1 No.,D-1 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1No.                                       | 1No.   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 4No.                                       | 4No.   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 6Mtr.                                      | 6Mtr.  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-1 No.,D-1 No.                         | W-1 No.,D-1 No.                                      |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                         | W-1N0., D-1 No.                                      |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                   | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1No.                                    | 1No.   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 4No.                                    | 4No.   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 6Mtr.                                   | 6Mtr.  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | The State of the                           |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   | ***************************************              |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not-proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                         | W-1N0., D-1 No.                                      |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                   | 2-No.  |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-4N0., D-2 No.                            | W-4N0., D-2 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Rcof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Ccurt yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sirk Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | 1 No.                                      | 1 No.  |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 No.                                      | 1 No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1 No.                                      | 1 No.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                                 | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                             | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                            | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-1 No.                            | W-1N0., D-1 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                               | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                      | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                    | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                                  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                               | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                               | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                                 | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                               | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                                  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                                  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                                  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | 2 2 2 2 6                                  |  |
| 1          | WC Pan/Commode (18,19)   | 1 No.                                      | 1 No.  |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1 No.                                      | 1 No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1 No.                                      | 1 No.  |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate  | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm   | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)   | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)  | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not Proposed   | Not Required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-1N0., D-2 No.  | W-1N0., D-2 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed   | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32  | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum  | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum  | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1 NO.  | 1 NO.  |
| 11         | UPVC Vent (24)   | Not-proposed   | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm   | 129.93 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)  | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm   | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed   | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm  | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm   | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm  | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm  | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed   | Not Required   |
| 21         | Soak Pit   | Not proposed   | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed   | 15 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | Control of the Contro |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed   | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed   | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed   | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed   | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed   | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed   | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed   | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed   | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed   | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed   | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed   | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed   | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed   | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement   |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,37,39)                              | 420.96 sqm                              | 420.96 sqm   |
| 2          | Ceiling Plaster (2,38)   | 5.63 sqm (avg)                          | 9.00 sqm   |
| 3          | Wall Plaster (3,37)  | 27.74 sqm (avg)                         | 45.5sqm  |
| 4          | D/W/V Frame/Chaukhat (4,16,17,18)                              | Not Proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla (4,19,20,21,25,26,27,28,29,30,31)          | W-2N0., D-2 No.                         | W-2N0., D-2 No.  |
| 6          | Brick work(5.6.7)  | Not Proposed                            | Not Required   |
| 7          | PCC Apron (11,12,13,14)  | 29.32                                   | 29.32  |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.17cum                                 | Not required   |
| 9          | R.C.C. slab,chhajja rack(9,10)                                 | 0 .35 cum                               | 0.35cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | Not-proposed                            | Not-required   |
| 11         | UPVC Vent (24)   | Not-proposed                            | Not-required   |
| 12         | External Wall Painting (1,41)                                  | 129.93 sqm                              | 129.93 sqm   |
| 13         | Mcsquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 73.9 sqm                                | 73.9 sqm   |
| 15         | Court yard drain(5,6,7)  | Not Proposed                            | Not Required   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (35,36)                 | 28.27 sqm                               | 28.27 sqm  |
| 17         | Granite kitchen top( 6,7,16,17)                                | 2.67 sqm                                | 2.67 sqm   |
| 18         | Vitrified flooring (45)  | 34.80 sqm                               | 34.80 sqm  |
| 19         | Painting D/W/V (32)  | 10.12 sqm                               | 10.12 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 15 sqm   |
| B .        | Sanitary/Sewage/Water Supply System                            |   | A Property of the Control of the Con |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                               | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                          | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                         | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                       | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                       | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                               | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                              | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                            | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                               | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                               | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | 3 1  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | W-2No.D-2NO.                               | W-2No.,2-No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-2N0.,D-2NO.                              | W-2NO,D-2NO.   |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 2-No.                                      | 2-No.  |
| 8          | CP Brass Shower (28)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (29)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (30)                                      | 3-No.                                      | 3-No.  |
| 11         | CP Brass Basin Mixer (31)                                      | 1-No.                                      | 1-No.  |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 0.56 m(avg.)                               | 6 m  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | ,  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-1NO.                                     | D-1NO.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1NO.                                     | D-1NO.   |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 2-No.                                      | 2-No.  |
| 11         | UPVC Vent (24)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | 1-No.                                      | 1-No.  |
| 8          | CP Brass Shower (28)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (29)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (30)                                      | 3-No.                                      | 3-No.  |
| 11         | CP Brass Basin Mixer (31)                                      | 1-No.                                      | 1-No.  |
| 12         | PVC Rain Water pipe (32,33,34)                                 | 0.56 m(avg.)                               | 6 m  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-2NO., W-1No.                             | D-2NO., W-1No.   |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-2NO.                                     | D-2NO.   |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-03 No., W-2 No.                          | D-03 No., W-2 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-03 No., W-2 No.                          | D-03 No., W-2 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | Land to the second second                  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | . Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | - 0  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement   |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | The state of the s |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7.         | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | . Not Proposed                             | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as per present site requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                               | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                          | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                         | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                       | D-01 No., W-1 No.                                    |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                       | D-01 No., W-1 No.                                    |
| 6          | Brick work(5.6.)   | 0.60 cum                                | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                               | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                              | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                            | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                               | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Rcof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                               | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3.         | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | 2  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. |                       | Name of Items/work<br>(TS Sr. No.)            | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|-----------------------|---|--|--|
| A          | Civil works           |   |  |  |
| 1          | Internal Wa           | Il Distemper (1,40,41,42)                     | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plas          | ter (2,3,9)                                   | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster          | (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Fran            | ne/Chaukhat (16,17,18)                        | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shut            | ter/Palla 19,20,21,27,28,29,30,31)            | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(           | 5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.          | C.C. Apron                                    | proposed                                   | Required   |
| 8          | RCC Lintel            | Beam and chajja (8)                           | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitch          | nen slab (9,10)                               | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid d           | oor shutter ver L/B, (22,23)                  | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent             | (24)  | Not proposed                               | Not Required   |
| 12         | External Wa           | all Painting (40,41,42)                       | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Ja           | li (42,43)                                    | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatm           | nent (Brick-coba) approved by M.M.M.U.T.      | Not proposed                               | Not Required   |
| 15         | Court yard o          | drain(14,15)                                  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile          | e, Wall/Floor, L/B, Kitchen (36,37)           | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitch         | hen top( 34,35)                               | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/V          | W/V (33,33)                                   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank           | Land of the Control of the Control            | Not proposed                               | Not Required   |
| 21         | Soak Pit              |   | Not proposed                               | Not Required   |
| 22         | Chemical Co<br>MMMUT) | oating for wet surface (Extra ItemApproved by | Not proposed                               | 12 sqm   |
| В          | Sanitary/Se           | wage/Water Supply System                      |  |  |
| 1          | WC Pan/Co             | mmode (18,19)                                 | Not Proposed                               | Not Required   |
| 2          | Wash Basin            | (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainle          | ss steel (23)                                 | Not Proposed                               | Not Required   |
| 4          | Jet for Com           | node S Steel (24)                             | Not Proposed                               | Not Required   |
| 5          | PVC Conne             | ction pipe(25)                                | Not Proposed                               | Not Required   |
| 6.         | PVC Waste             | pipe(26)                                      | Not Proposed                               | Not Required   |
| 7          | CP Brass Bi           | bcock long body (27)                          | Not Proposed                               | Not Required   |
| 8          | CP Brass Sh           | ower (28)                                     | Not Proposed                               | Not Required   |
| 9          |                       | all Mixer (29)                                | Not Proposed                               | Not Required   |
| 10         | CP Brass Ar           | ngle Valve (30)                               | Not Proposed                               | Not Required   |
| 11         | CP Brass Ba           | sin Mixer (31)                                | Not Proposed                               | Not Required   |
| 12         |                       | Vater pipe (32,33,34)                         | Not Proposed                               | Not Required   |
| C1         |                       | on work/Rewiring                              | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            | 1    | attended to the  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                      |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement   |
|------------|--|--|--|
| A          | Civil works  |  | a control of the cont |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UFVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mcsquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2 .        | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | 52.3 sqm                                   | 52.3 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                               | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                          | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                         | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                       | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                       | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                               | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                              | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                            | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                               | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                           | 12.35 sqm  |
| 14         | Roof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                            | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                               | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                            | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                            | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                            | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                            | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                            | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                            | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                            | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,40,41,42)                           | 190.32sqm                                  | 190.32 sqm   |
| 2          | Ceiling Plaster (2,3,9)  | 2.03 sqm (avg)                             | 5.0 sqm  |
| 3          | Wall Plaster (3,38)  | 20.04 sqm (avg)                            | 35 sqm   |
| 4          | D/W/V Frame/Chaukhat (16,17,18)                                | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-01 No., W-1 No.                          | D-01 No., W-1 No.  |
| 6          | Brick work(5.6.)   | 0.60 cum                                   | 0.60 cum   |
| 7          | Flooring, P.C.C. Apron   | proposed                                   | Required   |
| 8          | RCC Lintel Beam and chajja (8)                                 | 0.022 cum                                  | .022 cum   |
| 9          | R.C.C. kitchen slab (9,10)                                     | 0 .158 cum                                 | 0.158 cum  |
| 10         | PVC solid door shutter ver L/B, (22,23)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (24)   | Not proposed                               | Not Required   |
| 12         | External Wall Painting (40,41,42)                              | 147.62sqm                                  | 147.62 sqm   |
| 13         | Mosquito Jali (42,43)  | 7.18 sqm(avg)                              | 12.35 sqm  |
| 14         | Rcof treatment (Brick-coba) approved by M.M.M.U.T.             | Not proposed                               | Not Required   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (36,37)                 | 30.2 sqm                                   | 30.2 sqm   |
| 17         | Granite kitchen top( 34,35)                                    | 2.74 sqm                                   | 2.74 sqm   |
| 19         | Painting D/W/V (33,33)   | 51.18 sqm                                  | 51.18 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 12 sqm   |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (18,19)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (22)  | Not Proposed                               | Not Required   |
| 3          | Sink Stainless steel (23)                                      | Not Proposed                               | Not Required   |
| 4          | Jet for Commode S Steel (24)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(25)  | Not Proposed                               | Not Required   |
| 6          | PVC Waste pipe(26)   | Not Proposed                               | Not Required   |
| 7          | CP Brass Bibcock long body (27)                                | Not Proposed                               | Not Required   |
| 8          | CP Brass Shower (28)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (29)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (30)                                      | Not Proposed                               | Not Required   |
| 11         | CP Brass Basin Mixer (31)                                      | Not Proposed                               | Not Required   |
| 12         | PVC Rain Water pipe (32,33,34)                                 | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.50 sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-No.,W-1No.                               | W-1No.,D-No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,w-1No.                              | W-1No,D-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sgm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 2No.                                       | 2-No.  |
| 8          | CP Brass Shower (27)   | 3-No.                                      | 3-No.  |
| 9          | CP Brass Wall Mixer (28)                                       |  | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | 1-No.                                      | 1-No.  |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



CIV. A.E.UPR.N.S.S.

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.50 sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-1No., W-1No.                             | D-1No.W-No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-1,D-1                                    | W-1NO,D-1NO.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.50 sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-1No., W-1No.                             | D-1No.W-No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-1No.                                     | W-1NO,   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity<br>as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.50 sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-1No., W-1No.                             | D-1No.W-No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-1No.                                     | W-1NO,   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.50 sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | W-1No.                                     | W-1No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-3No.D-3No. V-7No.                        |  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7.         | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.2 sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-1No.                                  | D-1No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.                                  | D-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11.        | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.2 sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not -Proposed                           | Not-Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.                                  | D-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | I-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| - 2        | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 15.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 38.5sqm  |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-3No.                                  | D-3No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-3No.                                  | D-3No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 10.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not-Proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-3No.                                     | D-3No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Scak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | <del> </del>                               |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqrn                                 | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 10.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 42.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not-Proposed                               | Not-required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-2No.,W-2No.                              | D-2No.,W-2No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22 .       | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  | *******  |
| 1          | WC Pan/Commode (17,18)   | Not-Proposed                               | Not-Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 10.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 42.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not-Proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | Not-Proposed                            | Not-required   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not-Proposed                            | Not-Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   | · · · · · · · · · · · · · · · · · · ·                      |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 10.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 42.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not-Proposed                            | Not-required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | Not-Proposed                            | Not-required   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | Tooking to                              | <del></del>  |
| 1          | WC Pan/Commode (17,18)   | I-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| CI         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 10.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D- 2No.,V-2No.                          | D- 2No.,V-2No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D- 2No.,V-2No.                          | D- 2No., V-2No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 7 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   | 2,1,1  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| - 5        | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Cu A.E.UPR.N.S.S.

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | W-1No.                                  | W-1No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D- 3No.,W-3No.V-3No.                    | D- 3No., W-3No. V-3No.                                     |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 9 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



A.E.,U.P.R.N.S.S.

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-INo.                                  | D-1No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D- 1No.                                 | D- 1No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                   | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 9 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| C1         | Electrication work-Kewning                                     | Hot Hoposed                             | Not required   |

J.E., UPRNSS

A.E.,U.P. R.N.S.S.

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  | <del></del>  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | . 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | D-1No.,W-1No.                              | D-1No.,W-1No.  |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,W-1No.                              | D-1No.,W-1No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 9 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                      | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,W-1No.                              | D-1No.,W-1No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 9 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                      | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,W-1No.                              | D-1No.,W-1No.,V-1-No                                       |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1-No.                                      | 1-No.  |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 9 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | T 19 19 2 2 2                              |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | I-No.                                      | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11 .       | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 32.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | W-INo.                                     | W-1No.   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-3No.,W-3No.,V-3No.                       | D-1No., W-1No., V-3No                                      |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                      | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | W-1No.                                  | W-1No.   |
| - 5        | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-3No.,W-3No.,3No.                      | D-3No.,W-3No.,3No.   |
| 6.         | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | , |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-2No.,                                 | D-2No.,  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | INo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,W-1No.                           | D-1No.,W-1No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Kewning                                   | 1101 x Toposou                          | Tiotroquiou  |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| I          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No.,W-1No.                           | D-1No.,W-1No.  |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | INo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Scak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| I          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| l          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | W-2No.                                  | W-2No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   | 9  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate          | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  | -  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                                   | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                                   | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                                     | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                                   | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum  | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.  | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.   | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                                    | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm  | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                                     | Not Required   |
| 21         | Soak Pit   | Not proposed                                     | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                                     | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | <del>                                     </del> | (  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                                     | Not Required   |
| 2          | Wash Basin (21)  | 1-No.  | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.  | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                                     | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.  | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.  | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.  | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.  | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.  | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.  | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                                     | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                                     | Not Required   |
| C1         | Electrification work/Kewiring                                  | 140t i Toposed                                   | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | INo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | I-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sgm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| CI         | Electrification work/Kewiring                                  | Not Floposed                            | Not Kequired   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| . 6        | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | I-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Angle Valve (29)  CP Brass Basin Mixer (30)           | Not Proposed                            | Not Required   |
|            |  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Floposed                            | Not Kequited   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | 317  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Angle Valve (29) CP Brass Basin Mixer (30)            | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sgm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10 -       | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| C1         | Dieth meation work Xewning                                     | NotTroposed                             | Not required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | lNo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | <u> </u>                                | 201 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                    |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
|            | CP Brass Wall Mixel (20)  CP Brass Angle Valve (29)            | 2-No.                                   | 2-No.  |
| 10         | CP Brass Angle Valve (29)  CP Brass Basin Mixer (30)           | Not Proposed                            | Not Required   |
| 11         |  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11. <b>32</b> sqm                       | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | lNo.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                      | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| . 3        | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                      | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 2No.                                    | 2No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | I-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 2No.                                    | 2No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | 1                                       |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Kewiring                                  | 110t Floposed                           | 110t Required  |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | INo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
|            | CP Brass Angle Valve (29) CP Brass Basin Mixer (30)            | Not Proposed                            | Not Required   |
| 11         |  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not 1 toposed                           | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | 193                                     |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   | <del></del>  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                            | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                            | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
|            | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| 11<br>C1   | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  | · · · · · · · · · · · · · · · · · · ·                      |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | lNo.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | Not Proposed                               | Not Required   |
| 9          | CP Brass Wall Mixer (28)                                       | Not Proposed                               | Not Required   |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| CI         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| I.         | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 2No.                                    | 2No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| CI         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 2No.                                    | 2No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | 1-No.                                   | 1-No.  |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | 1-No.                                   | 1-No.  |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| CI         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | 200 200                                 |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | 7                                       |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | I-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm .                             | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | lNo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | 1.0                                     |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No."   |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | lNo.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quartity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | lNo.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work (TS Sr. No.)                                | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
|            | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |
| C1         | Electrification works rewriting                                | 130t Floposod                           | Tot Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | INo.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
|            |  | 2-No.                                   | 2-No.  |
| 10         | CP Brass Angle Valve (29)                                      |   |  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| - 1        | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | lNo.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11.        | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 2No.                                    | 2No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            | <u> </u>                                |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3-No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
|            | CP Brass Angle Valve (29)  CP Brass Basin Mixer (30)           | Not Proposed                            | Not Required   |
| 11         |  | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | 110t Hoposed                            | 1101 Required  |



Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | - 40                                    |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | - 8 sqm  |
| B          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |



J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Angle Valve (29) CP Brass Basin Mixer (30)            | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed  Not Proposed              | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  | . %  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                               | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   | A HINSON AND A CONTRACTOR                                  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   | 2  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

## **Ch/I/2**

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

### Kha/I/1

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS<br>Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|--|--|
| A          | Civil works  |  |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                                  | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                             | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                             | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                               | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                             | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                   | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                   | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                    | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                      | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                       | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                                  | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                              | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                                  | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                                  | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                    | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                                  | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                               | Not Required   |
| 21         | Soak Pit   | Not proposed                               | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                               | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |  |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                               | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                      | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                      | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                               | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                      | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                      | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                      | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                      | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                      | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                      | 2-No.  |
| 11         | CP Brass Angle Valve (29) CP Brass Basin Mixer (30)            | Not Proposed                               | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed  Not Proposed                 | Not Required   |
|            |  |  | 1  |



### Kha/I/2

Residence wise checklist/Inventory of Proposed work

Name of Work: Special Repair of Residences at MMMUT, Gorakhpur

Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  | i                                       |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

### Kha/I/3

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

## Ch/I/1

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick-work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | lNo.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17 -       | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E., UPRNSS

# **Ch/I/1**

Residence wise checklist/Inventory of Proposed work
Name of Work: Special Repair of Residences at MMMUT, Gorakhpur
Agency: UPRNSS, NirmanPrakhand-I, Gorakhpur

| Sr.N<br>o. | Name of Items/work<br>(TS Sr. No.)                             | Provisions/ Quantity as per TS Estimate | Provisions/ Quantity as<br>per present site<br>requirement |
|------------|--|---|--|
| A          | Civil works  |   |  |
| 1          | Internal Wall Distemper (1,44,45,46)                           | 132.28sqm                               | 132.28 sqm   |
| 2          | Ceiling Plaster (2,43)   | 12.50sqm (avg)                          | 12.0 sqm   |
| 3          | Wall Plaster (3,42)  | 35.77sqm (avg)                          | 40.00sqm   |
| 4          | D/W/V Frame/Chaukhat (20)                                      | Not proposed                            | Not Required   |
| 5          | D/W/V shutter/Palla 19,20,21,27,28,29,30,31)                   | D-1No., W-1No.                          | D-1No., W-1No.   |
| 6          | Brick work(8,9,10,18)  | 1.23 cum                                | 1.23 cum   |
| 7          | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 8          | RCC Lintel Beam and chajja (11)                                | 0.26 cum                                | .3 cum   |
| 9          | R.C.C. kitchen slab (12,13)                                    | .08 cum                                 | 0.09 cum   |
| 10         | PVC solid door shutter ver L/B, (26,27)                        | 1-No.                                   | 1-No.  |
| 11         | UPVC Vent (28)   | 1No.                                    | 1No.   |
| 12         | External Wall Painting (40,41,42)                              | 77.04 sqm                               | 77.04 sqm  |
| 13         | Mosquito Jali (47)   | 2.13 sqm(avg)                           | 4.00 sqm   |
| 15         | Court yard drain(14,15)  | 0.208 cum                               | 0.25 cum   |
| 16         | Ceramic Tile, Wall/Floor, L/B, Kitchen (40,41)                 | 11.82 sqm                               | 11.82 sqm  |
| 17         | Granite kitchen top( 34,35)                                    | 1.8 sqm                                 | 1.8 sqm  |
| 19         | Painting D/W/V (33,33)   | 19.42 sqm                               | 19.42 sqm  |
| 20         | Septic Tank  | Not proposed                            | Not Required   |
| 21         | Soak Pit   | Not proposed                            | Not Required   |
| 22         | Chemical Coating for wet surface (Extra ItemApproved by MMMUT) | Not proposed                            | 8 sqm  |
| В          | Sanitary/Sewage/Water Supply System                            |   |  |
| 1          | WC Pan/Commode (17,18)   | Not Proposed                            | Not Required   |
| 2          | Wash Basin (21)  | 1-No.                                   | 1-No.  |
| 3          | Sink Stainless steel (22)                                      | 1-No.                                   | 1-No.  |
| 4          | Jet for Commode S Steel (23)                                   | Not Proposed                            | Not Required   |
| 5          | PVC Connection pipe(24)  | 2-No.                                   | 2-No.  |
| 6          | PVC Waste pipe(25)   | 1-No.                                   | 1-No.  |
| 7          | CP Brass Bibcock long body (26)                                | 3–No.                                   | 3-No.  |
| 8          | CP Brass Shower (27)   | 1-No.                                   | 1-No.  |
| 9          | CP Brass Wall Mixer (28)                                       | 1-No.                                   | 1-No.  |
| 10         | CP Brass Angle Valve (29)                                      | 2-No.                                   | 2-No.  |
| 11         | CP Brass Basin Mixer (30)                                      | Not Proposed                            | Not Required   |
| C1         | Electrification work/Rewiring                                  | Not Proposed                            | Not Required   |

J.E.,UPRNSS